Historic, Archive Document

Do not assume content reflects current scientific knowledge, policies, or practices.



F7692F0

FOREST PRODUCTS RESEARCH IN PICTURES

NO. 66

VALUE OF DECAY PREVENTATIVES DEMONSTRATED



OCT 1928

U. S. FOREST SERVICE
MADISON. WISCONSIN

The mine timber marked "3" was installed after treatment with zinc chloride in 1908 and it is still sound after 17 years of service. The untreated timber marked with the arrow is decayed and due for early replacement. This timber was installed only four years ago to replace a treated timber which had been in service for 14 years. The original treated cap of this set, seen supported by the decayed timber, is sound in its eighteenth year of service.

Photograph by Forest Products Laboratory, U. S. Forest Service



